

## DIRECTORATE OF INTELLIGENCE

# Imagery Analysis Service Notes

19 June 1970

25X1

CIA internal use only

**Top Secret** 

25X1

COPY 81 25X1
PAGES 6

DECLASS REVIEW by NIMA/DOD

19 June 1970

CENTRAL INTELLIGENCE AGENCY Directorate of Intelligence Imagery Analysis Service

IMAGERY ANALYSIS SERVICE NOTES NO. 17/70


#### CONTENTS

	<u>Page</u>	
USSF		
	Photographic Identification of Naval Assault Units 2	
	Aluminum Industry Expanded 4	
		25X6
NORT	TH VIETNAM	_
	Iron Production Resumed at Thai Nauven Combine 6	

-1-

TOP SECRET

25X1



25X1	Approved For Release 2002/06/09: SECRET 8T04759A009700010062-3	25X1
		25X1
	<u>USSR</u>	
	Aluminum Industry Expanded	
25X1	A photographic study shows that the Soviet aluminum industry has expanded considerably mainly in south-central Siberia.	
25X1 25X1	the Soviets had II aluminum plants in operation. Shows that new aluminum plants have been put into operation at Bratsk, Krasnoyarsk and Irkutsk (see Figure I). A total of 24 potrooms are operating at the three new plants and eight additional potrooms are actively under construction. Based on the size of the new plants as determined from photography, when completed they will be capable of producing more aluminum than all the other plants combined. Their production capacity may be even larger, as Soviet reports indicate that electrolytic cells of a higher amperage are being used.	
25X1	new alumina plants have been put into operation at Achinsk and Pavlodar, also in south-central Siberia. These two plants appear designed to process low-grade aluminum ores.	
		25X1
•		
	-4-	725X1
	TOP SECRET	

25X1D

#### NORTH VIETNAM

Iron Production Resumed at Thai Nguyen Combine	
For the first time since the Thai Nguyen Iron and Steel Combine was put out of operation by bombing in mid-1967, the North Vietnamese have restored one of the damaged blast furnaces to operational status. On smoke was emanating from one of the three blast furnaces in the iron production area, indicating that the	(10
plant was operating. There was no evidence that the other blast furnaces or the open-hearth furnaces are operational.	
Since one of the large fabrication buildings has been partially reconstructed, a pipeline has been installed between the blast furnaces and the coke by-products section, and the substation has apparently been repaired with the transformers probably replaced.	
25	5X1

. -6-

### **Top Secret**

**Top Secret**